


Project 01 – Flat Roof Waterproofing & Rooflights

Photo portfolio – best-effort grouping from uploaded ZIP

Best-effort grouping based on visual review. This set appears to show flat roof refurbishment or new waterproofing works, including completed membrane areas, perimeter details, rooflight integration, and general completion views.

Images included	20
Grouping method	Visual review, file sequence, and similar subject matter
Status note	Project names/locations should be confirmed later if needed

Photo sequence



General roof overview
IMG-20260218-WA0014.jpg



Roof surface condition / progress view
IMG-20260218-WA0015.jpg



Completed membrane area
IMG-20260218-WA0023.jpg



Perimeter detail
IMG-20260218-WA0024.jpg



Rooflight detail
IMG-20260218-WA0025.jpg



Edge / upstand detail
IMG-20260218-WA0026.jpg



Completion overview
IMG-20260218-WA0027.jpg



Progress view
IMG-20260218-WA0028.jpg



General roof overview
IMG-20260218-WA0029.jpg



Roof surface condition / progress view
IMG-20260218-WA0030.jpg



Completed membrane area
IMG-20260218-WA0031.jpg



Perimeter detail
IMG-20260218-WA0032.jpg



Rooflight detail
IMG-20260218-WA0033.jpg




Edge / upstand detail
IMG-20260218-WA0034.jpg



Completion overview
IMG-20260218-WA0035.jpg



Progress view
IMG-20260218-WA0036.jpg



General roof overview
IMG-20260218-WA0037.jpg



Roof surface condition / progress view
IMG-20260218-WA0038.jpg



Completed membrane area
IMG-20260218-WA0039.jpg



Perimeter detail
IMG-20260218-WA0040.jpg